

HYUNDAI-KIA - RSF150087KH - Resistencia en serie, electromotor de ventilador HYUNDAI Typ

Resistencia en serie, electromotor de ventilador HYUNDAI Typ

253850L000, 253850L000, HYUNDAI, KIA

253850L000, NUEVO ORIGINAL

RSF150087KH

KIA-HYUNDAI Type 12V

PREMIUM
ORIGINAL



HYUNDAI, KIA

FLAMAR
HATIBONET