

HQ - RTF410002HQ - ROTOR NUEVO HITACHI Type 12V 60Amp 94,40mm

ROTOR NUEVO HITACHI Type 12V 60Amp 94,40mm

RT200390, 23708AA000, L150-71001, L150-91006, L155-21002, L155-71001, 23708AA000, L150-71001, L150-91006, L155-21002, L155-71001 RT200390, RT200390, NUEVO HIGH QUALITY

RT200390, RT200390, NUEVO HIGH QUALITY

RTF410002HQ

HITACHI Type 12V 60Amp 94,40mm

HQ
HIGH QUALITY



FLAMAR
HATIDORSET