

APP - 30F0701 - KIT REPARACIÓN CABLES INYECTORES

2324096 - A0255455026

CHEVROLET: CAPTIVA, ORLANDO; CITROËN: C4 GRAND PICASSO II, C4 PICASSO II, DS5, JUMPY, JUMPY | DISPATCH; FORD: KUGA II | ESCAPE, MONDEO V; FORD USA: EDGE; HYUNDAI: H-1 Cargo | iLOAD | i800 | H300, H-1 Travel | i800 | MONTANA, i20 I, i20 II, i30, ix20; INFINITI: Q50; JEEP: COMPASS; KIA: CEE"D, CEE"D Sportswagon, PRO CEE"D, RIO III, VENGA; MERCEDES-BENZ: CLA, CLA Shooting Brake, CLASE A, CLASE B Sports Tourer, CLASE C, CLASE C T-Model, CLASE E, CLASE E T-Model, CLASE GLA, CLASE GLK, CLASE M, CLASE S, CLASE V, CLS, CLS Shooting Brake, SLK, SPRINTER 3-t, SPRINTER 3,5-t, SPRINTER 4,6-t, SPRINTER 5-t, VIANO, VITO MIXTO, VITO, VITO Mixto(W447), VITO Tourer; OPEL: ANTARA A; PEUGEOT: 3008, 3008 SUV, 308 II, 308 SW II, 5008, 508 I, 508 SW I; SEAT: IBIZA IV, IBIZA IV ST; SKODA: FABIA II, ROOMSTER; SSANGYONG: ACTYON SPORTS I, ACTYON SPORTS II | MUSSO, KORANDO, RODIUS II | TURISMO, TIVOLI; VW: POLO V

