

HQ - ARF640404HQ - ARR NUEVO DENSO Type 12V 1,40kW 9T CW

ARR NUEVO DENSO Type 12V 1,40kW 9T CW

2280004370, 1280000403, 128000-0403, 2280001314, 228000-1314, 228000437, 228000-437,
2280004370, 2280004371, 228000-4371, 2280004372, 228000-4372, 2280004374, 228000-4374,
2280004390, 228000-4390, 2280004391, 228000-4391, 2280004840, 228000-4840, 2280804374, 228080-
4374, 28100-08020, 28100-20550-71, 28100-20551-71, 28100-20557, 28100-20571, 28100-20572, 28100-
22000, 28100-23810-71, 28100-34040, 28100-34042, 28100-34043, 28100-34044, 28100-34052, 28100-
34053, 28100-35020, 28100-35040, 28100-35060, 28100-35140, 28100-U2100, 28100-U2100-71, 28300-
22003, 28300-22003-71, TOYOTA, VW

2280004370, NUEVO HIGH QUALITY TOYOTA, VW

2280004370, NUEVO HIGH QUALITY

ARF640404HQ

DENSO Type 12V 1,40kW 9T CW

HQ
HIGH QUALITY



TOYOTA, VW

FLAMAR
HATIDORSAL