

WOODAUTO - SDV3021 - BENDIX FORD (dientes) =23F4504

BENDIX FORD (dientes) =23F4504

DELCO/FORD257T11000AB 97CA11000AB IS7U1100BC YC1U11000AB "257T11000AB /
97CA11000AB / IS7U11000BC / YC1U11000AB 1S7U-11000-BA 1S7U-11000-BB 1S7U-11000-BC 2S7T-
11000-DA 2S7T-11000-DB 2S7T-11000-DC 2S7T-11000-DA YC1U-11000-AB YC1U-11000-AC ?YC1U-
11000-AD YC1U-11000-AE YC1U-11000-AF" /136633 SD357, SD337, F90Z11350A,F5DZ11350A,
E9OZ11350A, E90Z11350A,E5DZ11350A 1057661, 1076141, 1085273,1151642, 1205240, 1367529,
1379703,1388569, 1X4U11000AA, 2S7T11000AA,2S7T11000AB

