

## HQ - RGF110152HQ - REGULADORES

### REGULADORES

UCB150, 000028000010, 1865974M1, 1897699M91, 23133-Q9000, 28000, 28710252, 345773M91, 3474604M91, 3476714M91, 37701, 37703, 37705, 37707, 37707A, 54048473, 54048473, 54048600, 54205986, 54205986, 54206177, 54206177, 54206448, 54206448, 54206467, 54206467, 54206645, 54206645, 54206688, 54207336, 54207336, 54208417, 592972, 6133746, 84AB-10316-AA, 940038133, 940038133010, A554711A, BAU4919, BAU5265, BAU5815, BAU5958, EGR356, FBU2243, FBV2243, RTC5044, RTC5370, RTC5670, UCB148, UCB148X, UCB150, UCB150X, UCB151, UCB151X, UCB152, 592972, NUEVO HIGH QUALITY

592972, NUEVO HIGH QUALITY 592972, NUEVO HIGH QUALITY

592972, NUEVO HIGH QUALITY

# RGF110152HQ

LUCAS Type 12V

**HQ**  
HIGH QUALITY



FLAMAR  
INTERNATIONAL