

HQ - RTF320004HQ - ROTOR NUEVO DENSO Type 12V 70Amp 89,00mm

ROTOR NUEVO DENSO Type 12V 70Amp 89,00mm

RT200602, 0212003100, 0212004670, 021200-4670, 0212004770, 021200-4770, 0212005760, 021200-5760, 0212006150, 021200-6150, 0212006151, 021200-6151, 0212006870, 021200-6870, 0212006871, 021200-6871, 31101-PD2-024, 31101PD20240, 31101-PD2-0240, 0212003100, 0212004670, 021200-4670, 0212004770, 021200-4770, 0212005760, 021200-5760, 0212006150, 021200-6150, 0212006151, 021200-6151, 0212006870, 021200-6870, 0212006871, 021200-6871, 31101-PD2-024, 31101PD20240, 31101-PD2-0240RT200602, RT200602, NUEVO HIGH QUALITY

RT200602, RT200602, NUEVO HIGH QUALITY

RTF320004HQ

DENSO Type 12V 70Amp 89mm

HQ
HIGH QUALITY**FLAMAR**
RETIRORES