

HQ - RTF220004HQ - ROTOR NUEVO DENSO Type 12V 75Amp 89,00mm

ROTOR NUEVO DENSO Type 12V 75Amp 89,00mm

RT200601, 0212002330, 0212002610, 021200-2610, 0212002960, 021200-2960, 0212002962, 021200-2962, 0212002963, 021200-2963, 0212005060, 021200-5060, 0212005160, 021200-5160, 0212005860, 021200-5860, 0212006691, 021200-6691, 27330-63020, 27330-63021, 27330-72100, 27330-72101, 8-94410984-0, 0212002330, 0212002610, 021200-2610, 0212002960, 021200-2960, 0212002962, 021200-2962, 0212002963, 021200-2963, 0212005060, 021200-5060, 0212005160, 021200-5160, 0212005860, 021200-5860, 0212006691, 021200-6691, 27330-63020, 27330-63021, 27330-72100, 27330-72101, 8-94410984-0 RT200601, RT200601, NUEVO HIGH QUALITY

RT200601, RT200601, NUEVO HIGH QUALITY

RTF220004HQ

DENSO Type 12V 75Amp 89mm

HQ
HIGH QUALITY**FLAMAR**
INTERNATIONAL