

HQ - RTF610002HQ - ROTOR NUEVO HITACHI Type 12V 16G 103,30mm

ROTOR NUEVO HITACHI Type 12V 16G 103,30mm

RT200392, 23108V7200, L160-31007, L160-41005, L170-71000, 23108V7200, L160-31007, L160-41005, L170-71000RT200392, RT200392, NUEVO HIGH QUALITY

RT200392, RT200392, NUEVO HIGH QUALITY

RTF610002HQ

HITACHI Type 12V 16G 103,30mm

HQ
HIGH QUALITY



FLAMAR
HATIDIONET