

HQ - RTF820002HQ - ROTOR NUEVO HITACHI Type 12V 55Amp 16G 94,40mm

ROTOR NUEVO HITACHI Type 12V 55Amp 16G 94,40mm

RT200432, L15051004, L155-41001, L155-81001, L15051004, L155-41001, L155-81001 RT200432,
RT200432, NUEVO HIGH QUALITY

RT200432, RT200432, NUEVO HIGH QUALITY

RTF820002HQ

HITACHI Type 12V 55Amp 16G 94,40mm

HQ
HIGH QUALITY



FLAMAR
HATIDORSET