

HQ - RTF110652HQ - ROTOR NUEVO LUCAS Type 24V 89,50mm

ROTOR NUEVO LUCAS Type 24V 89,50mm

54208671, 54208671, 5420867, 54208671, 5420867RT200488, RT200488, NUEVO HIGH QUALITY

RT200488, RT200488, NUEVO HIGH QUALITY

RTF110652HQ

LUCAS Type 24V 89,50mm

HQ
HIGH QUALITY



FLAMAR
HATIBONG